


# Nuffield Oxford Hospital

Store Room Project

## Removal of Asbestos Insulation Behind Paint Work.

Here at Midlands Asbestos Solutions Ltd we have recently completed a large Store room clearance to the Nuffield Oxford Hospital for a large commercial client. The rooms involved had been subject to a previous asbestos removal project some years ago but this was not carried out to a suitable standard at the time. Midlands Asbestos Solutions acted quickly and efficiently to arrange a site visit to discuss all of the options with the client and representatives of the hospital. Following lengthy discussions on site we gave the client a free no obligation quotation to remove all of the traces of asbestos to the brick walls inside the store room by means of dustless blasting, giving the client a paint free room that is back to a bare brick finish. The client and Hospital were happy to go ahead with the works as per our competitive quotation and we immediately began planning the works and submitting all the relevant notifications to the HSE. Once we arrived on site to commence the asbestos removal works the Midlands Asbestos Solutions Ltd Contracts Manager and Director were present on site to perform a full hand over to the site staff which is standard with all large commercial projects. The works were due to be carried out over a 9 day period and this included removing all asbestos contamination to the store room and adjacent rooms, We assisted the client in ensuring that all relevant telecoms boxes were sealed and secure to prevent any damage prior to the works.

During the project our asbestos removal supervisor carried out audits on site staff and we were visited by the HSE who commented on the cleanliness and effectiveness of the site and the works being carried out. The asbestos removal works were completed 1 day early and all plant and equipment was removed from site before Midlands Asbestos Solutions staff left site. This meant that the client could be handed back a clean and safe to use area with no hired plant still awaiting collection. See the below before and after photos to show how, here at Midlands Asbestos Solutions we could transform your contaminated space into a workable area safe and asbestos free for all to use.



## Client Testimonial

“On behalf of Galliford Try Building East Midlands, We would like to pass on our many thanks to you both & everyone at Midlands Asbestos Solutions, with reference to the asbestos residue cleaning works carried out to the above project within the existing external ground floor store room. (In a controlled live environment). Please pass on our collective thanks to your team on site who carried out the works on site & a special thanks to your onsite supervisor David Cooper & team. The way your team have conducted themselves on site with me & with the manages at Nuffield Hospital is a credit to everyone involved, in which shows when we had a HSE executive officer visited site & gave us a clean bill of health, with the works enclosure, documentation, all in place with the comments such as exemplary. We will definitely be engaging with you Midlands Asbestos Solution on other projects in the near future.

Again thank you all”



Midlands Asbestos Solutions  
Unit 8 Crompton Road, Ilkeston  
Derbyshire DE7 4BG

t: 0115 932 6521  
e: [enquiries@midlandsasbestossolutions.co.uk](mailto:enquiries@midlandsasbestossolutions.co.uk)  
w: [www.midlandsasbestossolutions.co.uk](http://www.midlandsasbestossolutions.co.uk)